

WPU-7700 Release Notes

Product: WPU-7700

SW version: v 2.4.0

Release Date: May 21, 2009

UniData Communication Systems Inc.

Proprietary and Confidential

COPYRIGHT NOTICE

UniData Communication Systems is registered trademarks of UniData Communication Systems Inc. Other referenced trademarks are trademarks (registered or otherwise) of the respective trademark owners.

This document is confidential and proprietary to UniData Communication Systems Inc. No part of this document may be reproduced, stored, or transmitted in any form by any means without the prior written permission of UniData Communication Systems Inc.

Information furnished herein by UniData Communication Systems Inc., is believed to be accurate and reliable. The authors have used their best efforts in preparing this material. These efforts include the development, research, and testing of the theories and programs to determine their effectiveness.

However, UniData Communication Systems assumes no liability for errors that may appear in this document, or for liability otherwise arising from the application or use of any such information or for any infringement of patents or other intellectual property rights owned by third parties which may result from such application or use. The products, their specifications, and the information appearing in this document are subject to change without notice.

Printed in Korea

© 1998-2009 by UniData Communication Systems Inc. All rights reserved.

VoIP 단말 Release Notes Changed lists

1. Changed lists

- Adding functions / Fixing bug
 - Can not call fast dials end with '0'
 - Despite of changing phone number when sending Text messages, received message's sender is not changed.
 - Insert common phrases when writing Text messages
 - Icon image does not correspond with key in a symbol input unit.
 - Delete unused sub menu in SMS setting menu(7. Broadcast Msg)
 - Simultaneous bell and vibration effects
 - Bugs in characters when connecting in disabled state of PC Sync
 - No Error message when entering wrong password
 - Cursor in calendar is not moved when current time setting
 - Unnecessary submenu in Ping test
 - Not disappear cancel menu of soft key menu under Admin menu
 - The bug in sub soft menu in Diagnose Network
 - Set location is not correspond with world time picture
 - Displayed wrong time in checking text message when changing time format
 - MWI acts incorrectly when received MWI Message(SIP NOTIFY) one after another
 - Cannot upload downloaded phone book file in PC sync
 - Strange characters are occurred when selecting common phrase without saved common phrase
 - Vibration is disappeared in manner mode when receiving SMS
 - Unnecessary scroll bar in menu
 - Cannot check message directly when setting Lock Message
 - Same Number is saved continuously when Setting Spam number
 - Display wrong notice window when entering Reset to default menu
 - Counting incorrectly when received new messages Over 100
 - Cannot test Diagnostic RTP
 - Change LCD/LED TEST string in Admin menu
 - Display wrong notice window in Group settings
 - Cannot receive e1_mac.ini failed to file upgrade in Auto Provision
 - Low battery sound volume as setting
 - Ringers volume is changing when ringing alarm during using Ringing louder

VoIP 단말 Release Notes Changed lists

■ Ringers volume is change when generating battery/recharge system alert during using Ringing louder

- Ringers volume is different with setting when playing sound in Menu-Sound-Ringers during using Ringing louder
- Phone is rebooted automatically when recharging in cradle during turning off the phone
- Activate all functions related to vibration
- Terminal is rebooted after sending SMS when entering sever address to Message Server
- Problem not to parsing body when first character value of SIP message body is '\0'
- Screen is turn off when getting a phone call during ringing alarm
- Dial tone is heard when pushing the send button without entering number to Dial window
- Display soft menu characters incorrectly in dial screen
- Phone sometimes reboot in sound effect menu
- Supporting Display Name when call and receiving
- Phonebook file synchronization via Auto-Provisioning Server
- Modify character Trans mission to Transmission
- Danish language stings support
- Ringers and ring tone setting icon is changed when setting alarm

^{*} Red sentence is request from customers

VoIP 단말 Release Notes Persons in charge

2. Persons in charge

	Primary	Secondary
Name	Patrick Kim	Yohan Kim
Position	FAE Manager	FAE
E-mail	dykim@udcsystemscom	yhkim@udcsystems.com
TEL	82-2-3443-3390 (Ex 224)	82-2-3443-3390 (Ex 331)

- END -